



APPENDIX N
PHOTOGRAPHS OF PHASE II INVESTIGATION
ACTIVITIES

SWMU 11
Chemical Munitions Storage Area



)))

Groundwater Sampling SWMUs 11 and 19





SWMU 19
Building 533 Foundation
Empty Drum Storage Area



)))

SWMU 19

Septic Tank



)))

Monitoring Well Installation SWMU 19




Soil Organic Vapor Survey

SWMU 19 and 33c




SWMU 20 – Excavation Activities



Septic Tank




Backhoe Operation along Septic Pipe Trench



Backhoe Operation along Septic Pipe Trench


SWMU 20 – Building 520 (Crating Facility)


Inside



SWMU 20 – Building 520 (Crating Facility)



Outside






SWMU 33-Building 536
Chemical Agent Munitions
Disposal System Salt Storage

Monitoring Well – S-115-94 in foreground



)))

SWMU 33b
Inside Building 536





SWMU 33c



SWMU 37 - Test Pit Excavation Activities



SWMU 37



SWMU 37- Representative Test Pit



SB-37-12



SB-37-16



SB-37-19



SB-37-20

SWMU 37 - Test Pit Excavation Activities



SB-37-14



SB-37-18



SB-37-19



SB-37-20



SWMU 37
Slag Piles and Bomb Fragments





SWMU 37
Slag Piles and Bomb Fragments

